## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	921	324/158.1.CCLS. AND LAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:32
L2	457	1 AND PROBE	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:42
L3	131564	WIRING SAME BOARD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:43
L4	4538	3 AND PROBE	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:43
L5	641	4 AND MULTILAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:43
L6	91359	438/14- "18" AND MULTILAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:43
L7	9	438/14-18 AND MULTILAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:44
L8	269	438/14-18.CCLS. AND MULTILAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:44
L9	67973	"87" AND PROBE	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:44

5/13/06 6:48:03 PM Page 1

## **EAST Search History**

L10	1313	"324"/\$.CCLS. AND MULTILAYER	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:44
L11	656	10 AND PROBE	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:45
L12	12502	MULTILAYER SAME WIRING SAME BOARD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:45
L13	780	12 AND FABRICATION	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:45
L14	78	13 AND PROBE	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:45

5/13/06 6:48:03 PM Page 2

## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L15	14	(probe same detects same defects same multilayer same wiring same element same supplementing same unit same mounts same additional same elements same multilayer same wiring same board same under same fabrication same no same defect smae probe same tests same fabrication same additional same supplement).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/05/13 18:47

5/13/06 6:47:52 PM Page 1